

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	797	408/204.ccls. or 408/206.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
2	BRS	L2	1022	408/238.ccls. or 408/239r.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
3	BRS	L3	729	279/75.ccls. or 408/240.ccls.	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
4	BRS	L4	2457	3 or 2 or 1	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
1	2006/06/08 14:50			
2	2006/06/08 14:50			
3	2006/06/08 14:50			
4	2006/06/08 14:50			

	Type	L #	Hits	Search Text	DBs
5	BRS	L5	15	4 and @py>"2005"	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
6	BRS	L6	1100	arbor and shank	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
7	BRS	L7	638	6 and screw	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
8	BRS	L8	23	7 and adaptor	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
5	2006/06/08 14:56			
6	2006/06/08 14:57			
7	2006/06/08 14:58			
8	2006/06/08 15:11			

	Type	L #	Hits	Search Text	DBs
9	BRS	L9	48	6 and adaptor	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
10	BRS	L10	25	9 not 8	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
11	BRS	L11	1469	hole adj saw	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
12	BRS	L12	32	11 and adaptor	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
9	2006/06/08 15:12			
10	2006/06/08 15:14			
11	2006/06/08 15:15			
12	2006/06/08 15:15			

	Type	L #	Hits	Search Text	DBs
13	BRS	L13	100	11 and adapter	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B
14	BRS	L14	114	13 or 12	US- PGPUB; USPAT; EPO; JPO; DERWEN T; IBM_TD B

	Time Stamp	Comments	Error Definition	Errors
13	2006/06/08 15:15			
14	2006/06/08 15:15			